

Message

**From:** [Nonresponsive based on revised scope]@erllc.com]  
**Sent:** 7/9/2020 4:06:27 PM  
**To:** Wagner, Christine [Wagner.Christine@epa.gov]  
**Subject:** RE: [EXT]Shiloh Church rd offspecs.

Will do.  
Btw, this is the first i heard about this situation.

Sent from my Verizon, Samsung Galaxy smartphone

----- Original message -----  
From: "Wagner, Christine" <Wagner.Christine@epa.gov>  
Date: 7/9/20 11:57 (GMT-05:00)  
To: [Nonresponsive based on revised scope]@erllc.com>  
Subject: Re: [EXT]Shiloh Church rd offspecs.

Can you verify with ACV if they ran a closed cup test or if this was just a hazmat result?

Thank you  
Chris

> On Jul 9, 2020, at 11:25 AM, [Nonresponsive based on revised scope]@erllc.com> wrote:  
>  
> Chris,  
> Please c below.  
> We r working it out with acv. Will advise on solution.  
> May need ur signature on new profiles.  
> Will let u know.

> Sent from my Verizon, Samsung Galaxy smartphone

> ----- Original message -----  
> From: [Nonresponsive based on revised scope]@acvenviro.com>  
> Date: 7/9/20 08:28 (GMT-05:00)  
> To: [Nonresponsive based on revised scope]@erllc.com>, [Nonresponsive based on revised scope]@erllc.com>, [Nonresponsive based on revised scope]@erllc.com>  
> Subject: [EXT]Shiloh church rd offspecs.

> \*\*\*CAUTION\*\*\* This email originates from a source outside the company. Please use caution when opening attachments, clicking on links, or following the senders request.  
> Please see attached offspec. I am not sure if I sent his to you already or not, I can't find the email. SO I apologize if I did.  
>  
> The WD03- The drum flashed below 140F. Do you need the drum #? We need to figure out why it may have flashed so we can do a new profile and get this resolved.  
> The WD01- One drum flashed below 140F. Same for this: Do you need the drum #? We need to figure out why it may have flashed so we can do a new profile and get this resolved.

> Let me know your thoughts so we can get this cleared up

> [ACVEnviro]<<https://gcc01.safelinks.protection.outlook.com/?url=https%3A%2F%2Fwww.acvenviro.com%2Fdecon%2F&data=02%7C01%7CWagner.Christine%40epa.gov%7C4c702bcd98144bc11dc308d824220d18%7C88b378b367484867acf976aacbeca6a7%7C0%7C0%7C637299075967898231&sdata=67bVHOxsBNcD%2FPWSnS21zwxoJWr55Y0QCYE7tqhd4ik%3D&reserved=0>>

> Ask about COVID-19 Protect, Prevent & React<<https://gcc01.safelinks.protection.outlook.com/?url=https%3A%2F%2Fwww.acvenviro.com%2Fdecon%2F&data=02%7C01%7CWagner.Christine%40epa.gov%7C4c702bcd98144bc11dc308d824220d18%7C88b378b367484867acf976aacbeca6a7%7C0%7C0%7C637299075967898231&sdata=67bVHOxsBNcD%2FPWSnS21zwxoJWr55Y0QCYE7tqhd4ik%3D&reserved=0>>

> **Nonresponsive based on revised scope**  
> / Assistant Customer Service Manager - Brokers  
>  
> 550 Industrial Drive , Lewisberry , PA 17339

> t: **Nonresponsive based on revised scope**  
>  
> e: **Nonresponsive based on revised scope**@acenviro.com<mailto:**Nonresponsive based on revised scope**@acenviro.com>

>  
>  
>  
>  
>  
>  
>  
>  
> From: **Nonresponsive based on revised scope**@acenviro.com  
> Sent: Thursday, July 9, 2020 7:33 AM  
> To: **Nonresponsive based on revised scope**@acenviro.com  
> Subject: Attached Image

>  
>  
>  
>  
> Confidentiality Warning: This e-mail and any attachments contain information intended only for the use of the individual or entity named above. If the reader of this e-mail is not the intended recipient or the employee or agent responsible for delivering it to the intended recipient, any dissemination, publication or copying of this e-mail is strictly prohibited. Although this email has been scanned for malware, the sender does not accept any responsibility for any loss, disruption or damage to your data or computer system that may occur while using data contained in, or transmitted with, this e-mail. If you have received this e-mail in error, please immediately notify by return e-mail. Thank you.  
> <image612301.png>  
> <3954\_001.pdf>